Release Notes for:
RoboSHOT 12 HDBT and RoboSHOT 30 HDBT

****
Date 12/08/2017
v1.2.0

Updates and Fixes:
- Added codec control mode for compatibility with Cisco and Polycom codecs
- Updated time zone information
- Added ability to import configurations from previous versions of software
- Misc. internal code improvements

Known issues:
- If selected time zone is deprecated during a time zone information update, it will default back to UTC

****

Date: 7/19/2017
v1.1.0

Updates and Fixes:
- Improved gamma handling over serial connections.
- Updated gamma range for RoboSHOT 30 HDBT cameras.
- Updated HDBaseT parameters for enhanced device interoperability.
- Added audio to IP streaming on HDBT sources
- Added ability to route incoming HDBT audio to either the IP stream output or both the IP stream output and the local HDMI output.
- Updated for wide dynamic range setting over RS-232.
- Misc. internal code improvements

****

Date: 1/19/2017
v 1.0.1

Updates and Fixes:
- Corrected motor configuration on RoboSHOT 12 HDBT units home position.
- Updated default IP streaming settings to "720p Better".
- Misc. internal code improvements

****

Date: 11/28/2016
v1.0.0

Initial Release

****

Additional Information:
For instructions on how to update your firmware, please see the product installation guide on our website at
www.vaddio.com

Thank you for your continued support of Vaddio products. Please contact Vaddio with any questions at 763-971-4400 or through our website.