

Release Notes for:
RoboSHOT® 12 & RoboSHOT 30 system models

Release Information:

Date: 7/12/2018

V2.3.0

Notes:

- New Features:
 - o Added CODEC compatibility mode for Polycom® 3xx/5xx/7xx series Codecs.
 - o Added CODEC compatibility mode for Cisco® SX-20 and SX-80 series CODECs. (For SX-20 CODECs, Vaddio recommends CODEC's firmware be updated to latest "CE" series firmware for best operation)
- Security Updates/Improvements
 - o Added ability to disable the Telnet server on the device.
- Control / Configuration Updates
 - o Added ability to import configuration settings exported from previous versions of software.
 - o Added Telnet control commands for absolute position control.
 - o Improved ability via Telnet control to allow finer detailed position setting for zoom.
 - o Updated syntax for "network ping count" Telnet command.
 - o Enhanced support for USB joystick control.
 - o Updated system time zone data.
 - o Interoperability improvements with Internet Explorer® 9 through IE11.
 - o Various web UI improvements.
- Various other minor updates.

Date: 10/12/2017

v.2.2.2

Updates and Fixes:

- Misc. internal code improvements

Date: 9/11/2017

v2.2.1

Updates and Fixes:

- Added soft DIP switch and Telnet command to turn the camera LED on and off
- Soft DIP switch improvements
- Firmware update improvements, motor firmware update
- Misc. internal code improvements

Date: 9/1/2017
v2.2.0

Updates and fixes:

- Telnet command enhancements
- Firmware update improvements
- Misc. internal code improvements

Date: 11/7/2016
v2.1.2

Updates and Fixes:

- Miscellaneous internal code improvements

Date: 9/28/2016
v2.1.1

Updates and Fixes:

- Motor parameters updated for 30x cameras to reduce vibration
- Upper tilt limit increased
- Updates to work with RoboTRAK
- Misc. internal code improvements

Date: 5/18/2016
v2.0.2

Updates and fixes:

- Serial control stability improvements with AVBridge Matrix Pro

Date: 1/25/2015
v2.0.1

Updates and fixes:

- Fix for inverted IR forwarding dipswitch behavior
- Misc. internal code improvements

Date: 1/14/2016
v2.0.0

Updates and fixes:

- Correction for gamma value in home preset
- IP control and import/export support



Date: 7/31/2015

v1.1.0

- Correction for USB joystick PTZ speed control
- Added pan/tilt axis inversion control in the web UI
- Misc. internal code improvements

Date: 10/29/2014

v1.0

1.0.0 Initial Release

Additional Information:

For instructions on how to update your firmware, please see the product installation guide on our website at www.vaddio.com

Thank you for your continued support of Vaddio products. Please contact Vaddio with any questions at 763-971-4400 or through our website.

Vaddio is a brand of Milestone AV Technologies · www.vaddio.com · Phone 800.572.2011 / +1.763.971.4400 · Fax +1.763.971.4464 · Email info@vaddio.com

Visit us at support.vaddio.com for firmware updates, specifications, drawings, manuals, and technical support information. Vaddio, RoboSHOT, RoboTRAK, and AVBridge, are a trademark or registered trademark of Milestone AV Technologies. All other brand names or marks are used for identification purposes and are trademarks of their respective owners. In British Columbia, Milestone AV Technologies ULC carries on business as MAVT Milestone AV Technologies ULC.