

Release Notes for:
OneLINK HDMI Camera Extension Models

Release Information:

Date: 6/26/2018
v1.1.0

Notes:

- Various Security Updates
 - o Added ability to disable the telnet server on the device.
 - o Added ability to disable the HTTP server on the device. When this is disabled, HTTPS must be used to connect to the web UI.
 - o Added ability to configure HTTPS certificates from the web UI.
 - o Improved internal firewall settings.
 - o Disabled TLS v1.0 protocol.

- Various Control/Configuration Updates
 - o Updated web UI look & feel.
 - o Added support via Telnet control commands to request current temperature readings from a connected OneLINK HDMI device.
 - o Allow import of configuration exported from previous versions of software.
 - o Fix for hostname changes not being properly handled for DHCP.
 - o Updated system time zone data.
 - o Interoperability improvements with Internet Explorer 9 through IE11.
 - o Fix for web UI not rendering in Chrome when fonts.googleapis.com was unreachable.
 - o Various other minor updates.

- Various Functional Improvements/Updates
 - o Improved several items relating to increased HDBaseT performance.
 - o Improved SD card write performance enabling extended card life.
 - o Various other minor updates.

Date: 6/6/2016
v1.0.1

Notes:

- Update to work with RoboSHOT 20 UHD camera.
- Update to enable configuration data to be exported and imported when importing to the same firmware version as the exported file.

Date: 3/31/2016



v1.0.0

Initial Release

Additional Information:

For instructions on how to update your firmware, please see the product manual on our website at www.vaddio.com.

Thank you for your continued support of Vaddio products. Please contact Vaddio with any questions at 763-971-4400 or through our website.