

Release Notes for:
PrimeSHOT 20 HDMI

Release Information:

07/16/2018
V1.0.1

****Initial Release****

Known Issues:
When changing the streaming settings during an active IP streaming session, connection errors can occur, requiring a device reboot to recover.

Additional Information:

For instructions on how to update your firmware, please see the product manual on our website at www.vaddio.com.

Thank you for your continued support of Vaddio products. Please contact Vaddio with any questions at 763-971-4400 or through our website.